Pro-Bal 500
Packing List for PC500 Upgrade System
For SW2000 Stewart Warner
Soft Bearing (Horizontal Spring) Systems

Touch Screen Computer w/Eagle logo (Front holes plugged)

2 pcs ¼-20x1 SHCS w/nuts and washers (for mounting computer)

4x8x1/4 Plate for Mounting Computer with 2x2x6 square tubing

Position Indicator (Encoder) w/Cable, vertical post

U-Joint for Encoder

2 Magnets (one large, one small)

Balancing Instruction Manual

Windows Installation Disc

2 Piezo Sensors

2 Sensor Extension Leads

2 Sensor Filter Boards (No Enclosures)

Pickup Cable Set (17 foot left and 8.5 foot right)

1 Clay Stick