

Packing List for			Packed by:	
TS-5000 XL			Packing Date	
Packed	Description	Quantity	Notes	
	Setup and Operator's Manual	1		
	Foot Clamps for inline blocks	4		
	Closed Slotted Clamp Bars	4		
	Open Slotted Clamp Bars	4		
	1/2-13 clamp studs	4		
	Clamp Tapers	4		
	Short Jack Stands	2		
	Tall Jack Stands	2		
	Jack Stand Studs	4		
	Short Jack Stand Extensions	2		
	Long Jack Stand Extensions	4		
	V-8 Main Bar XL 41"	1		
	V-8 Head Cradle 41"	1		
	Cutter Plate Puller Plate	1		
	3/8-16 x 1 1/2 Screws for Puller Plate	2		
	3/4"-8 leveling bolts w/nuts	6		
	Leveling Pads	6		
	Sliding Indicator Bracket (mounted on ways)	1		
	Sliding Indicator w/collar and gage	1		
	Brass extension for Sliding Indicator	1		
	Cutter Height Indicator w/collar and gage	1		
	Head Clamp Spacers	12		
	Head Clamp Studs w/nuts 1/2-13x8	4		
	4" Cast Iron Parallels	2		
	8" Cast Iron Parallels	4		
	CBN Tool Holder on Cutter Plate	2		
	CBN Insert and Clamp w/plastic box	1		
	eye, hand, electrical safety labels	5		
	Forked Blue Terminals	4		
	Cutter Head Shipping Brackets	2		
	Spacer Bars for T-Slot Nuts	2		
	Available Options:			
	1710 Block Kit	1		\$2,500.00
	Additional CBN Cutter	1		\$195.00
	Additional PCD Insert	1		\$195.00